# TABLE OF CONTENTS

# **CHAPTER ONE - TESTING EQUIPMENT**

Laboratory

General

Sampling

Sample Reduction

Sieve Analysis

Decantation

Deleterious and Chert

Test Equipment Verification

Laboratory Set-Up

### **CHAPTER TWO - SAMPLING**

Sampling Techniques

Safety

Sample References

Size of Original Samples

Sample Type

Method of Sampling

Production Sampling

Stockpile Sampling

Sampling Directly from Trucks, Rail Cars, or Barges

### **CHAPTER THREE - SAMPLE REDUCTION**

Reducing a Sample to Test Size

Mechanical Splitter

Sand Splitter

Miniature Stockpile

Quartering

Size of Test Sample (After Splitting)

#### **CHAPTER FOUR - TESTING**

Gradation

Sieving

Decantation

Sieve Analysis Test

Fineness Modulus

Sieve Analysis for Dense Gradation materials

**Deleterious Materials** 

Deleterious Materials in Coarse Materials

Deleterious Materials in Natural Sand

**Crushed Particles** 

Flat and Elongated Particles

Clay Content

Fine Aggregate Angularity

Plastic Limit

Surface Moisture Tests

## **CHAPTER FIVE - AGGREGATE SPECIFICATIONS AND REQUIREMENTS**

Physical Quality Requirements

Fine Aggregates

Coarse Aggregates

**Physical Quality Tests** 

Absorption

Abrasion Resistance

Soundness

Deleterious

**Special Requirements** 

General Usage Requirements

Fine Aggregates

Coarse Aggregates

**Gradation Requirements** 

Fine Aggregates

Coarse Aggregates

B Borrow and Structure Backfill

Riprap

Aggregate Base

Subbase

Aggregate Pavements or Shoulders

**Summary of Gradation Requirements** 

# APPENDIX A

# Indiana Test Methods

202	Acid Insoluble Content of Fine Aggregates
203	Control Procedures for Classification of Aggregates
205	Acceptance Procedures for Dolomite Aggregates
206	Scratch Hardness of Coarse Aggregate Particles
207	Sampling Stockpiled Aggregates
209	Soundness of Aggregates by Freezing and Thawing in a Brine
	Solution
210	Class AP Coarse Aggregate for Concrete Pavement and Slab-on-
	Grade Concrete
212	Acceptance Procedures of Air Cooled Blast Furnace Slag for
	Leachate Determination
902	Verifying Sieves
903	Verifying Ovens
906	Verifying Mechanical Shakers
910	Verifying Balances

# APPENDIX B

# **AASHTO Test Methods**

T 2	Sampling of Aggregates
T 11	Materials Finer Than 75 μm (No. 200) Sieve in Mineral
	Aggregates by Washing
T 27	Sieve Analysis of Fine and Coarse Aggregates
T 84	Specific Gravity and Absorption of Fine Aggregate
T 85	Specific Gravity and Absorption of Coarse Aggregate
T 112	Clay Lumps and Friable Particles in Aggregate
T 248	Reducing Field Samples of Aggregate to Testing Size
T 304	Uncompacted Void Content of Fine Aggregate

# **ASTM Test Methods**

D 4791	Flat Particles, Elongated Particles, or Flat and Elongated Particles in Coarse Aggregate
D 5821	Determining Percent of Fractured Particles in Coarse Aggregate